


## **APPENDIX B**

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,412  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 21 Villas Drive, New Castle, Del.

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape Rectagular  
stories 1 1/2 stories  
bays  
wings
- b) Structural system
- c) Foundation masonry, (stucco over stone)  
materials  
basement
- d) Exterior walls  
materials wood  
color(s)
- e) Roof  
shape; materials gable, ridge to side, asphalt  
cornice  
dormers  
chimney location(s)
- f) Windows  
spacing  
type double hung  
trim wood  
shutters no
- g) Door  
spacing centered  
type 6 panel  
trim
- h) Porches  
location(s) front  
materials wood  
supports posts  
trim overhang in front  
no platform above
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION:      good   x        deteriorated           

remarks:

4. INTEGRITY: a) original site probably b) moved           

c) if moved, when and from where

d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: 1930's

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage \_\_\_\_\_ d) privy \_\_\_\_\_

e) shed      f) greenhouse      g) shop      h) gardens

i) icehouse      j) springhouse      k) other

describe:

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. **Surveyor:** Alan Tabachnick **Date of Form:** 5/11/88

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,412  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling.
2. STREET LOCATION: 21 Villas Drive, New Castle, DE
3. OWNER'S NAME: Frank Acierno TEL. #   
ADDRESS: 21 Villas Drive, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
x a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) Chrs, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A- Main House

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e) not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title ADI/CHRS  
BAHP: Name/Title \_\_\_\_\_

Date 5/11/88  
Date \_\_\_\_\_

FRANK ACTIERNO HOUSE N-12,412




Top: looking north; Bottom looking west



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12.413  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/06/14

1. ADDRESS OF STRUCTURE : 414 Christiana, Road, New Castle, Delaware

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape rectangle  
stories 1 & 1/2 story  
bays  
wings

b) Structural system

c) Foundation  
materials  
basement

d) Exterior walls artificial stone  
materials gray  
color(s)


e) Roof  
shape; materials gable side to side ridge  
cornice simple  
dormers yes  
chimney location(s) central

f) Windows double hung  
spacing  
type  
trim  
shutters

g) Door  
spacing  
type 1/2 wood, 1 1/2 glass  
trim

h) Porches  
location(s) door in front  
materials  
supports  
trim

i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good X deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site probably b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: main section could be old

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage x d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_

describe: \_\_\_\_\_

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).


10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12.413  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/C4/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: 414 Christiana Road, New Castle, DE
3. OWNER'S NAME: Vernon C. West TEL. #   
ADDRESS: 414 Christiana Road, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH.

# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - e. not eligible

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS

Date 5/11/88

BANP: Name/Title

Date


VERNON C. WEST HOUSE N-12,413



Top: looking north

CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,414  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 314 Christiana Road, New Castle, Delaware

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangle  
stories 1 & 1/2 stories  
bays  
wings
- b) Structural system
- c) Foundation masonry  
materials  
basement
- d) Exterior walls Asbestos Siding with brick entry  
materials  
color(s)
- e) Roof Asphalt  
shape; materials  
cornice  
dormers  
chimney location(s) front
- f) Windows  
spacing  
type double hung  
trim  
shutters no
- g) Door  
spacing center  
type  
trim
- h) Porches no  
location(s)  
materials  
supports  
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good X deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site X b) moved           

c) if moved, when and from where \_\_\_\_\_

d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: 30's - 40's

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage \_\_\_\_\_ d) privy \_\_\_\_\_

e) shed      f) greenhouse      g) shop      h) gardens

i) icehouse      j) springhouse      k) other

describe:

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

**USE BLACK INK ONLY**

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,414  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/72/04/7

1. NAME OF LOCUS: Dwelling
2. STREET LOCATION: 314 Christiana Road, New Castle, DE
3. OWNER'S NAME: C. Everet Mercer TEL. #   
ADDRESS: 314 Christian Road, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

## 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



Not to scale

## 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A- Main House

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS

Date 5/11/88


BAHP: Name/Title

Date

C. EVERET MERCER HOUSE N-12,414




Top: looking south; Bottom: looking southeast





CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,416  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 243 Christiana Rd. New Castle, Delaware

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangle  
stories 1 & 1/2 stories  
bays  
wings
- b) Structural system
- c) Foundation materials masonry  
basement yes
- d) Exterior walls materials  
color(s) stucco
- e) Roof  
shape; materials Ashpalt (broken gable)  
cornice  
dormers  
chimney location(s) end, block.
- f) Windows  
spacing  
type double hung  
trim  
shutters yes, now only front
- g) Door  
spacing side  
type  
trim
- h) Porches enclosed into general house  
location(s)  
materials  
supports  
trim
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good X deteriorated \_\_\_\_\_  
remarks: altered, possibly originally a commercial building

4. INTEGRITY: a) original site X b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_  
\_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: 1930's ?

6. ARCHITECT/BUILDER: \_\_\_\_\_  
\_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage \_\_\_\_\_ d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_  
describe: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,416  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/G4/7

1. NAME OF LOCUS: Dwelling
2. STREET LOCATION: 243 Christian Road, New Castle, DE
3. OWNER'S NAME: Robert T. Weaver TEL. #   
ADDRESS: 243 Christian Road, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215 699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



260

INDICATE NORTH ON SKETCH

# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main house

- 10. Comprehensive Planning: Upper peninsula zone
  - a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization


- 11. Evaluation:
  - a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

USE BLACK INK ONLY


Survey: Name/Title ADT/CHRS  
BAHP: Name/Title

Date 5/11/88  
Date

ROBERT T. WEAVER HOUSE N-12,416



Top: looking south; Bottom: looking south



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,415  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Christiana Road, 227

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape  
stories 2 1/2  
bays 2  
wings rear wing, 2 stories, 2 bays
- b) Structural system
- c) Foundation  
materials stone  
basement
- d) Exterior walls  
materials brick  
color(s) painted white
- e) Roof  
shape; materials gable roof, asbestos shingles  
cornice boxed wood  
dormers none  
chimney location(s) external brick at ridge, north facade
- f) Windows  
spacing  
type n) 6/1 D/H, 4/1 D/H e) paired 6/1 D/H s) 6/1 D/H,  
trim wooden sash  
shutters none
- g) Door  
spacing main door on north facade-wood with multi-paned window  
type Colonial Revival  
trim set in wooden broken triangular pediment
- h) Porches  
location(s) on N/E corner of structure  
materials wooden sheathed in asbestos shingles  
supports Doric wooden columns with shed roof  
trim
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

## Historic Structure Description

This 2 1/2 story 2 bay brick Colonial Revival dwelling stands with its gable end perpendicular to Route 273, at the entry road to the Timber Ridge Townhouses development. The house sits back off the road, with conifers along the north and south walls, while the east side of the property is landscaped with bushes and flowers. There is an in-ground pool to the immediate west of the house, and a one story gable roofed concrete block garage to the rear(south).

The north(main) facade is two bays in width, and 2 1/2 stories in height, with an external brick chimney at the ridge. The first story has two entrances, one to the east and west of the chimney base. The east entrance is a wooden door with a large multi-paned window. There is a wooden porch at this corner of the house, running from the eastern edge of the chimney base on the north facade, to approximately 5 feet along the eastern facade. This porch is supported by three Doric wooden columns, and has a shed roof. The entrance to the west of the chimney base is a one story projecting bay, capped by a gable roof. The entrance itself has an elaborate broken triangular pediment. The door itself is wooden panelled, with a small six paned window. The second story has two 6/1 windows, double hung with wooden frames. The attic story has two 4/1 double hung wooden windows.

The east facade has two bays. The first story has a paired 6/1 double hung wooden window on the south, and a triple 6/1 double hung wooden window on the north. The second story has two sets of paired 6/1 double hung wooden windows, located above the first story windows. All of the windows have wooden sills. Part of the north facade porch wraps around this facade, at the north corner.

The south(rear) facade has a projecting section, two bays wide, on the west. This section is two stories in height, with a hipped roof that ties into the main part of the house. The first story, south facade, has a door on the west side. The second story has two symmetrically placed 6/1 double hung wooden windows. Above these windows is a line of four 6/1 double hung wooden windows. This projecting rear section is only 6' in depth, with no fenestration on the east or west facades. The east section of the main house(south facade) has a 6/1 double hung wooden window on the first story, and an identical window directly above. There is a 6/1 double hung wooden window at the gable, which is sheathed in horizontal wood siding.

3. CONDITION: good xxx deteriorated \_\_\_\_\_  
remarks: \_\_\_\_\_

4. INTEGRITY: a) original site xxxx b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) does not appear to  
have been altered. There is a pool and new garage to E and S.

5. DATE OF INITIAL CONSTRUCTION: early 20th century

6. ARCHITECT/BUILDER: unknown

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage xxx d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other in ground pool

describe: Garage is 1 story, gable roof, with concrete block walls.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

This structure historically was used as a residence, and is currently a residence. No association with historic events or persons is known.

9. Primary References: (include location of reference).


10. Surveyor: Alan Tabachnick, CHRS, Inc. Date of Form: 5/29/87

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-2

FOR OFFICE USE ONLY


CRS # N-12,415  
Quad Newark East  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: 227 Christiana Road, New Castle, DE
3. OWNER'S NAME: Oak Hollow Associates TEL. #   
ADDRESS: 227 Christian Roa, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☒  
d) scattered buildings ☒ e) densely built up ☐ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

C-Pool

- 10. Comprehensive Planning: Upper Peninsula Zone
  - a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

- 11. Evaluation:
  - a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS  
NAHP: Name/Title

Date 5/11/88  
Date

OAK HOLLOW ASSOCIATES HOUSE N-12,415



Top: looking west; Bottom: looking south



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,411  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 182 Christiana Rd. New Castle, Del.

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangle  
stories 1 & 1/2 story  
bays  
wings
- b) Structural system
- c) Foundation masonry  
materials  
basement yes
- d) Exterior walls stucco over masonry, main part  
materials Dormer & porch- siding  
color(s)
- e) Roof  
shape; materials asphalt shingle  
cornice none or little  
dormers shed dormer in front  
chimney location(s) center
- f) Windows  
spacing double hung  
type  
trim  
shutters no
- g) Door  
spacing center  
type  
trim
- h) Porches  
location(s) enclosed entry  
materials  
supports  
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good X deteriorated \_\_\_\_\_  
remarks: altered

4. INTEGRITY: a) original site \_\_\_\_\_ b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: ?

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:  
a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage X d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_  
describe: \_\_\_\_\_

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,411  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: 182 Christiana Road, Ch New Castle, DE
3. OWNER'S NAME: Joseph L. Pasturski TEL. #   
ADDRESS: 182 Christiana Road, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - e. not eligible

INDICATE NORTH ON SKETCH.

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS


BAHP: Name/Title \_\_\_\_\_

Date 5/11/88  
Date \_\_\_\_\_

JOSEPH L. PASTURSKI HOUSE N-12,411




Top: looking north-east; Bottom: looking north





CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1

FOR OFFICE USE ONLY

CRS # N-12,409  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 185 Christiana Rd., New Castle

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape Rectange  
stories raise 1 1/2 story  
bays 2  
wings

b) Structural system

c) Foundation materials Masonry  
basement

d) Exterior walls materials Stucco on wood , "form stone" (front)  
color(s)


e) Roof shape; materials gable, with Shed-roofed dormer (front);  
cornice asphalt  
dormers center  
chimney location(s) little detail

f) Windows double-hung  
spacing  
type  
trim  
shutters

g) Door spacing center  
type wood panelled  
trim

h) Porches location(s)  
materials  
supports  
trim

i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good \_\_\_\_\_ deteriorated \_\_\_\_\_

remarks: ABANDONED

4. INTEGRITY: a) original site ? b) moved \_\_\_\_\_

c) if moved, when and from where \_\_\_\_\_

d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: 1930s

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage x <sup>(1-car)</sup> d) privy \_\_\_\_\_

e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_

i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_

describe: \_\_\_\_\_

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5-11-88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,409  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred NewCastle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: 185 Chrstiana Road, New Castle, DE
3. OWNER'S NAME: unknown TEL. #   
ADDRESS:
4. TYPE OF LOCUS: a) structure x b) district  c) archaeological site   
d) other
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field  b) cultivated field  c) woodland x  
d) scattered buildings  e) densely built up x f) other
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known  b) zoning  c) roads x d) developers   
e) deterioration  f) other
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 51188

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

- 10. Comprehensive Planning: upper peninsula zone
  - a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

- 11. Evaluation:
  - a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - e. not eligible

INDICATE NORTH ON SKETCH.

USE BLACK INK ONLY

Survey: Name/Title ADI/CHRS  
BAHP: Name/Title

Date 5/11/88  
Date

DWELLING N-12,409




Top: looking south-east; Bottom: looking south



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,410  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : 184 Christiana Rd., New Castle

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape rectangle  
stories 1 1/2  
bays  
wings
- b) Structural system
- c) Foundation Block  
materials  
basement
- d) Exterior walls "Stone" type block  
materials  
color(s)
- e) Roof  
shape; materials Asphalt  
cornice  
dormers  
chimney location(s)
- f) Windows Double-hung  
spacing  
type  
trim  
shutters No
- g) Door  
spacing  
type  
trim
- h) Porches  
location(s) Front  
materials Brick  
supports Brick Columns  
trim
- i) Interior details (if accessible)



SKETCH PLAN

USE BLACK INK ONLY

3. CONDITION: good ☒ deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site ☒ b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: 1920s-1930s

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage ☒ d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_  
describe: 2 car , same block

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY

CRS # N-12,410  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7


1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: 184 Christiana Road, New Castle, DE
3. OWNER'S NAME: unknown TEL. #   
ADDRESS:
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☐ e) densely built up ☒ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215 699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc DATE: 5/11/88

USE BLACK INK ONLY



# 8. SKETCH MAP

*Please indicate position of locus in relation to geographical landmarks such as streams and roads.*



# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

- 10. Comprehensive Planning: upper peninsula zone
  - a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

- 11. Evaluation:
  - a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

INDICATE NORTH ON SKETCH.

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS

BAHP: Name/Title \_\_\_\_\_

Date 5/11/88

DWELLING N-12,410




Top: looking north; Bottom: looking north-east



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,408  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/09/14

1. ADDRESS OF STRUCTURE : North side of Route 273, #160 "Tat-Tat"

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape Neo-Egyptian Temple Front  
stories 2  
bays 2  
wings Ranch house to rear

b) Structural system Concrete

c) Foundation  
materials Concrete  
basement

d) Exterior walls  
materials Concrete, poss. poured  
color(s) Pink


e) Roof  
shape; materials Flat, asphalt  
cornice Vernacular Egyptian Cornice  
dormers  
chimney location(s) in center of rear Ranch section

f) Windows  
spacing 2 tall, narrow on front facade  
type painted glass  
trim concrete sills  
shutters none

g) Door Double main door  
spacing  
type  
trim Painted Egyptian figures on door panels

h) Porches  
location(s)  
materials  
supports  
trim

i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good xxxx deteriorated \_\_\_\_\_  
remarks: has been maintained

4. INTEGRITY: a) original site xxxx b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: ca. 1950's

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage \_\_\_\_\_ d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other two-room concrete block bldg.

describe: Decorated like temple, painted pink with painting on exterior.

Gable metal roof, chimney, appears to date after the main temple was  
built.

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


The Temple was constructed as an Egyptian type temple for unknown use. It appears to have been used, and is currently used, to attract tourist attention.

9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/4/88

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-2

FOR OFFICE USE ONLY


CRS # N-12,408  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: TAT TAT - Dwelling Complex
2. STREET LOCATION: 160 Christian Road, New Castle, DE
3. OWNER'S NAME: John Hawkins TEL. #   
ADDRESS: 160 Christian Road, New Castle, DE
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☒ e) densely built up ☐ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215699-8006  
YOUR ADDRESS: 403 E. Walnut ST. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc DATE: 5/11/88

USE BLACK INK ONLY

## 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



## 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House/Temple

B-Small House

C-Pool

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title ADI/CHRS Date 5/11/88  
BAHP: Name/Title Date

## Architectural Description

"Tat-Tat", is a complex of two buildings, the main one was built in a Neo-Egyptian/Persian/Babylonian style in the middle 1950's. The building was not carried out with academic skill, and is a combination of different historical elements. The main building was originally constructed as a "ranch" house, one story, with a T plan. In the 1950's, a large two story temple front was constructed on the main facade of the "ranch" house. This massive front has two large piers on both sides, and two smaller narrow square pilasters framing the center door. The larger end piers extend past the exterior walls of the tower, and narrow considerably as they intersect with the cornice and roof. Between the outer and inner pilasters are narrow painted glass windows. These windows are approximately 1' wide and 7' in height. They rest on small concrete sills on both the first and second stories.

The central entrance is a double door covered in metal and decorated with a male and female (apparently Egyptian) figure. The door is topped with an Egyptian type fluted flat pediment that flairs outward. Above the door, centrally placed between the second story windows and pilasters, is a triangular decoration with an Egyptian Ankh painted upon it. The cornice is an exaggerated Egyptian/Persian type, constructed of wood and metal, and painted in alternating vertical stripes of blue, red, and green. It does not continue around the rear of the tower. The entire structure is covered in a smooth pink stucco (or cement) finish. There are single tri-partite windows on the second story, east and west facades of the tower. The windows are metal framed and swing outward. The original ranch house has also been covered in the pink finish. It has a flat roof, metal windows and doors, and has a cement chimney at the center of the building.

There is a second building in the complex. It is a small, two room concrete block structure with a gable roof, and is located to the southeast of the main building. This building is oriented with the gable running parallel to the main road. It has a center entrance with a metal door, and two glass block windows to either side. The roof is metal. There are many decorative elements applied to the building, including a painting of an Egyptian style horseman in a chariot on the south facade. Applied features include shields, spears, banner-poles, and other designs. This building is also painted pink, but it appears to post-date the main building.

## Significance

The Tat-Tat Temple is significant as one of the few Neo-Egyptian/Persian/Babylonian Temples in the United States. Although it is not a pure interpretation, or an accurate reconstruction, the unique quality of the complex lends significance.

There are many possible inspirations for the shape of the Tat-Tat Temple. It seems likely that the form was taken from a variety of sources. First, the Temple of Horace at Edfu. Its massing, slanted buttress type walls, and center entrance with a flaring cornice could have been borrowed here. The shape of the Temple can be seen in the main entrance of the Temple of Khons, Karnak, Egypt from 1198 B.C. (Coppstone 1969:53). The massive entry portal slims from base to the top, where it is capped by a narrow cornice. However, there

are also parallels with the Ziggurat at Ur, Chaldea in Mesopotamia, 2125-2025 B.C. The buttress form here was used for strength at a very early date, and is very similar to the large buttress type sections on the main facade of the Tat-Tat Temple.

The door surround appears to have been largely copied from The massive entrance arches at the Palace of Darius, Persepolis, from c.500 B.C. (Gardner 1980:59). This Persian Empire site probably influenced the design of the cornice at Tat-Tat, where the flaring and fluting is transposed into the vertical painted lines. The art used to decorate the building appears to be in an Egyptian style, and can be compared to various wall paintings found from 1500 B.C. on. This can be seen in many illustrations. (for example, the tomb of Nebamun(?), Thebes, c. 1450 B.C., the Temple of Horus, Edfu, or the tomb of Nefertari in the Valley of the Kings).

Thus it appears that Tat-Tat is a compilation of historic styles, Egyptian, Persian and Babylonian, and instead of being carried out in brick as in the Persian structures, or in sandstone, like the Egyptian structures, Tat-Tat was built using twentieth century technology, cement, and covered in a light coating of sand and painted pink (probably to resemble sand).

The "Tat-Tat" complex is unique to the project corridor, and to the region. A unique building style like this interpretation of Neo-Egyptian is not discussed in the Delaware Comprehensive Historic Preservation Plan. This building style is extremely rare, and few other examples of this type of architecture are known outside of the resort areas of Florida. As an expression of vernacular Egyptian style, with elements of other early Mesopotamian cultures, this complex has significance. In addition, since its construction in the 1950's, the complex has received constant care and upkeep, and the buildings are in very good condition. The main temple building is one of the few examples of this type of architecture in the United States, and as such is a significant element of Delaware's architectural fabric.



TAT TAT N-12,408



Top: looking north; Bottom: looking west



TAT TAT N-12,408




Top: looking north; Bottom: looking north



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1

FOR OFFICE USE ONLY

CRS # N-12,418  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Hares Corner
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape  
stories 1 1/2  
bays  
wings
- b) Structural system
- c) Foundation  
materials Block  
basement
- d) Exterior walls  
materials Brick  
color(s)
- e) Roof  
shape; materials Gable, ridge goes front to back  
cornice  
dormers  
chimney location(s) 2 on each side of roof
- f) Windows  
spacing  
type double-hung  
trim  
shutters yes
- g) Door  
spacing  
type wood, 6 panel  
trim
- h) Porches  
location(s) front  
materials wood  
supports 1/2 brick and 1/2 round columns  
trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION: good X deteriorated \_\_\_\_\_  
remarks: \_\_\_\_\_

4. INTEGRITY: a) original site X b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known) \_\_\_\_\_

5. DATE OF INITIAL CONSTRUCTION: circa. 1920

6. ARCHITECT/BUILDER: \_\_\_\_\_

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage X d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse \_\_\_\_\_ j) springhouse \_\_\_\_\_ k) other \_\_\_\_\_  
describe: recent 2 car, block

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:

9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,418  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: Hares Corner, New Castle, DE
3. OWNER'S NAME: unknown TEL. #   
ADDRESS:
4. TYPE OF LOCUS: a) structure ☒ b) district ☐ c) archaeological site ☐  
d) other ☐
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☐ b) cultivated field ☐ c) woodland ☐  
d) scattered buildings ☒ e) densely built up ☐ f) other ☐
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning ☐ c) roads ☐ d) developers ☐  
e) deterioration ☐ f) other ☐
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE:  #   
TITLE:  #   
TITLE:  #
8. YOUR NAME: Alan Tabachnick TEL. # 215-699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# C. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



Not to scale

## 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A- Main House

B-Garage

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

INDICATE NORTH ON SKETCH.

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS

Date 5/11/88

DAHP: Name/Title

Date

DWELLING N-12,418



Top: looking south; Bottom: looking south-west



DWELLING N-12,418




Top: looking south



CULTURAL RESOURCE SURVEY  
STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314




Form CRS-1  
FOR OFFICE USE ONLY

CRS # N-12,417  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : Hares Corner
2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

- a) Overall shape      Rectangle  
    stories            1 1/2 stories  
    bays  
    wings
- b) Structural system
- c) Foundation  
    materials           masonry  
    basement            yes
- d) Exterior walls  
    materials           wood siding  
    color(s)
- e) Roof  
    shape; materials    asphalt shingles  
    cornice  
    dormers  
    chimney location(s) <sup>yes</sup> middle
- f) Windows  
    spacing  
    type                double-hung, 2/2, pairs  
    trim  
    shutters            no
- g) Door  
    spacing  
    type                centered  
    trim                wood
- h) Porches  
    location(s)        front, enclosed  
    materials  
    suppoorts  
    trim
- i) Interior details (if accessible)



USE BLACK INK ONLY

3. CONDITION:      good    X                          deteriorated \_\_\_\_\_

remarks: \_\_\_\_\_

4. INTEGRITY: a) original site X b) moved \_\_\_\_\_  
c) if moved, when and from where \_\_\_\_\_  
d) list major alterations and dates (if known)

5. DATE OF INITIAL CONSTRUCTION: 1930s (?)

6. ARCHITECT/BUILDER:

7. RELATED OUTBUILDINGS:

a) barn \_\_\_\_\_ b) carriage house \_\_\_\_\_ c) garage   X   d) privy \_\_\_\_\_  
e) shed \_\_\_\_\_ f) greenhouse \_\_\_\_\_ g) shop \_\_\_\_\_ h) gardens \_\_\_\_\_  
i) icehouse          j) springhouse          k) other \_\_\_\_\_

describe:

8. BRIEFLY DISCUSS THE ORIGINAL AND SUBSEQUENT USES OF THE STRUCTURE. NOTE ANY ASSOCIATIONS WITH HISTORIC EVENTS OR PERSONS:


9. Primary References: (include location of reference).

10. Surveyor: Alan Tabachnick Date of Form: 5/11/88

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY  
LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-3

FOR OFFICE USE ONLY


CRS # N-12,417  
Quad Wilm. South  
SPO map # 08-09-33  
Hundred New Castle  
DOCUMENT 20-06/78/04/7

1. NAME OF LOCUS: Dwelling Complex
2. STREET LOCATION: Hares Corner, New Castle, DE
3. OWNER'S NAME: unknown TEL. # \_\_\_\_\_  
ADDRESS: \_\_\_\_\_
4. TYPE OF LOCUS: a) structure ☒ b) district \_\_\_\_\_ c) archaeological site \_\_\_\_\_  
d) other \_\_\_\_\_
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field \_\_\_\_\_ b) cultivated field \_\_\_\_\_ c) woodland \_\_\_\_\_  
d) scattered buildings ☒ e) densely built up \_\_\_\_\_ f) other \_\_\_\_\_
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning \_\_\_\_\_ c) roads \_\_\_\_\_ d) developers \_\_\_\_\_  
e) deterioration \_\_\_\_\_ f) other \_\_\_\_\_
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_
8. YOUR NAME: Alan Tabachnick TEL. # 215 699-8006  
YOUR ADDRESS: 403 E. Walnut St. North Wales, PA 19454  
ORGANIZATION (if any) CHRS, Inc. DATE: 5/11/88

USE BLACK INK ONLY

# 8. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



# 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

A-Main House

B-Garage

10. Comprehensive Planning: upper peninsula zone
- a. Time Period(s) 1880-1940 urbanization & suburbanization
  - b. Cultural Concept suburbanization

11. Evaluation:
- a. Settlement & Development
  - b. Cultural Historic & Ethnic Issues
  - c. Built Environment
  - d. Material Culture
  - ☒ e. not eligible

INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

Survey: Name/Title ADT/CHRS  
NAHP: Name/Title

Date 5/11/88  
Date

DWELLING N-12,417



Top: looking south; Bottom: looking south-east

